## GenX Connector Pin Assignment

GenX Motion Controller Features

GenX Processor Pin Assignment

Extruder Heater is controlled by HEAT – temperature read by THERM.

Heat Bed is controlled by HEAT_2 – temperature read by THERM2.