




Modifying Sanguinololu PCB from v1.1 to v1.2

Mod Functionality Status: REVIEWED by JOEM & VERIFIED as FUNCTIONING CORRECTLY by HAIRYKIWI

KEY

Redundant track:  and suggested cutting location.

New wire:  Kynar Insulated 30AWG or similar.

Redundant pad:  (Extension Pin Header only.)

REAR VIEW OF BOARD SHOWN

