






2. solder
3. component
4. componentmask
5. soldermask
6. plated-drill
7. topsilk
8. bottomsilk
9. topassembly
10. bottomassembly
11. fab
























There are 8 different drill sizes used in this layout, 369 holes total.

Symbol	Diam. (Inch)	Count	Plated?
Y	0.030	148	YES
+	0.040	149	YES
x	0.050	9	YES
o	0.055	20	YES
□	0.060	16	YES
▽	0.070	16	YES
⊕	0.081	4	YES
⊗	0.126	7	YES

Title: (unknown) - Fabrication Drawing  
Author: Markus Hittler  
Date: Don 17 M 2011 19:50:05 GMT UTC

